

# Release Notes Addendum

**VERSION 17.0.1** 

13-00122-000-BB

2023-09-22

#### **Patent Information**

This product may be protected by one or more patents.

For further information, please visit: www.grassvalley.com/patents/

#### **Copyright and Trademark Notice**

Grass Valley®, GV® and the Grass Valley logo and/or any of the Grass Valley products listed in this document are trademarks or registered trademarks of GVBB Holdings SARL, Grass Valley USA, LLC, or one of its affiliates or subsidiaries. All other intellectual property rights are owned by GVBB Holdings SARL, Grass Valley USA, LLC, or one of its affiliates or subsidiaries. All third party intellectual property rights (including logos or icons) remain the property of their respective owners.

Copyright ©2023 GVBB Holdings SARL and Grass Valley USA, LLC. All rights reserved.

Specifications are subject to change without notice.

#### **Terms and Conditions**

Please read the following terms and conditions carefully. By using Video Production Center documentation, you agree to the following terms and conditions.

Grass Valley hereby grants permission and license to owners of Video Production Center to use their product manuals for their own internal business use. Manuals for Grass Valley products may not be reproduced or transmitted in any form or by any means, electronic or mechanical, including photocopying and recording, for any purpose unless specifically authorized in writing by Grass Valley.

A Grass Valley manual may have been revised to reflect changes made to the product during its manufacturing life. Thus, different versions of a manual may exist for any given product. Care should be taken to ensure that one obtains the proper manual version for a specific product serial number.

Information in this document is subject to change without notice and does not represent a commitment on the part of Grass Valley.

Warranty information is available from the Legal Terms and Conditions section of Grass Valley's website (www.grassvalley.com).

#### Recycling

Visit www.grassvalley.com for recycling information.

Title K-FRAME Release Notes Addendum

Part Number 13-00122-000-BB Revision 2023-09-22 10:00

# K-Frame Release Notes Addendum, V17.0.1

#### **About this Manual**

IMPORTANT: The newest KAY-Panels requires V17.0.1 SW as a minimum. If you have purchased a new KAY Panel please ensure to upgrade the rest of your system to V17.0.1.

IMPORTANT: V17.0.1 is only supported by the GV K-Frame XP and GV K-Frame X (Video Production Center). It is recommended to update the SW and HAD on any spare controller boards you may have as well.

NOTE: Starting with V16.2.5 the Menu only uses port numbers 6130 and 6131 to communicate with the Frame.

**NOTE**: Bus Linking/Macros: V16.2.1 introduces a new Macro format. Macros of bus links created in V16.0.0 to V16.2.0 may not correctly translate to the new macro format. These macros will need to be corrected. The operator should validate that the Macro containing bus linking was translated correctly before using the macro in a show by running it and confirming the correct behavior. All other Macros should be properly translated.

**NOTE:** For K-Frame X systems: The V16.2.0 or later software includes changing the software operating system for the frame to Linux-based software (see K-FRM-X-UPG-LX-KIT for ordering). This change requires changing out the hard drives on the Frame Controller and Image Store Controller boards before installing the V16.2.0 or newer software. It also means that the frame console has significantly changed its console behavior and Secure Shell Protocol (SSH) improving network security by requiring passwords for logging into the frame console. The default username and password is "user" and "gvuser". Please be aware that your local engineering management may have changed this password. Please refer to the K-Frame XP Installation and Service Manual for changes. The X will act similarly to an XP as described in the manual.

The V16.2.6 software for the K-Frame X includes all of the bug fixes from V15.0.0 to V17.0.1 for the K-Frame XP that are applicable to the K-Frame X. Also, device control system, IP I/O cards, NMOS IS-04 and IS-05 and Gearbox boards have had significant updates since V14.7.x. This includes a number of menu screen changes.

This document includes "Resolved" and "Known" issues for K-Frame software version 17.0.1. See the K-Frame Release Notes, version 16.1 for Grass Valley Video ProductionCenter software update instructions.

#### **For More Information**

For information about installing, configuring, and operating K-Frame systems, see the K-Frame Video Production Center Documentation Libraries found on the Grass Valley website and on the USB thumb drive provided with your system.

#### **Known Issues**

## **Software Issues Resolved in Release 17.0.1**

| Area          | Issues  | ID         | Case ID  |
|---------------|---|------------|----------|
| Macro Editor: | Macro Editor missing names for first Keyer Value    | KFCK-27399 |          |
|               | when setting bus links.                             |            |          |
| Panel:        |   |            | 00805370 |
| Dissolve Rate | mode after pressing 'ENT' button, but Dissolve Rate |            | 00837204 |
|               | is recorded in the next available E-MEM registry.   |            |          |
| Multifunction |   | KFCK-27220 | 00834591 |
| Module:       | Priority and panel reset.                           |            |          |
| Kayenne Panel |   |            |          |

## **Software Issues Resolved in Release 17.0.0**

<INTERNAL RELEASE>

## **Software Issues Resolved in Release 16.2.6**

| Area          | Issues  | ID         | Case ID  |
|---------------|---|------------|----------|
| System:       | In certain situations, the gm id for the clock can    | KFCK-27345 | 00860378 |
| RTP Clock     | get erased.   |            |          |
| IP I/O:       | DHCP Server not sending Domain Name of the DNS        | KFCK-27318 | 00851060 |
| K-Frame XP    | server can cause IP IO boards to restart.             |            |          |
| K-Frame V, X, | Condition where two connections to the frame go       | KFCK-27335 | 00857029 |
| XP            | to sleep at the same time can cause a frame crash.    |            | 00851697 |
|               | Solution: This is caused by KSP or Menu's running on  |            |          |
|               | a PC that does not have sleep mode disabled.          |            |          |
| IP I/O: NMOS  | In certain conditions the IP I/O losses NMOS          | KFCK-27262 | 00840090 |
| K-Frame X, XP | Registration  |            |          |
| IP I/O:       | ANC Payload Type not updated from Menu to SDP         | KFKC-27475 |          |
| K-Frame X, XP | file  |            |          |
| IP I/O:       | In certain conditions IP boards are visible on the XP | KFCK-27314 | 00849130 |
| K-Frame XP    | frames but GVO NMOS does not recognize them           |            |          |

## **Software Issues Resolved in Release 16.2.5**

| Area                     | Issues  | ID         | Case ID                          |
|--------------------------|---|------------|----------------------------------|
| System:<br>K-Frame X, XP | On rare occasions, communication between the Panel(s) and Menu(s) to the Frame is lost and the Frame Crashes.  NOTE: Menu now only uses port numbers 6130 and 6131 to communicate with the Frame. |            | 00836027<br>00843291<br>00845842 |
| K-Frame XP               | When switching to Operating Mode 2160p 23.98Hz the video outputs lose or distort video.   | KFCK-27204 | 00833348<br>00835837             |

## **Software Issues Resolved in Release 16.2.4**

| Area                          | Issues   | ID         | Case ID  |
|-------------------------------|--|------------|----------|
| 2DPM:                         | In some circumstances transitioning from a 2DPM to   | KFCK-27211 | 00837029 |
| K-Frame XP                    | another source can cause a visible glitch.   |            |          |
| Key Store:<br>K-Frame XP      | Key Store does not work correctly since V16.2.3  | KFCK-27196 |          |
| IP I/O: NMOS<br>K-Frame X, XP | Routing multiple I/O board receivers reports as OK, but some inputs do not change their multicast address.                     | KFCK-27217 | 00831291 |
| IP I/O:<br>K-Frame X, XP      | Inputs with Video, and Ancillary essences may intermittently have a line at the boom of the video. Ancillary data is not read. | KFCK-27216 |          |
| IP I/O:<br>K-Frame X, XP      | Inputs are occasionally taking hits with V16.2.2   | KFCK-27208 | 00831389 |
| IP I/O:<br>K-Frame X, XP      | The VPID is not present on the output when in 1080i.   | KFCK-27197 |          |
| System:<br>K-Frame XP         | Video identified as a different color space (Rec2020 / Rec709) then the suite may have its color shifted.                      |            | 00832964 |
| Power Monitor<br>K-Frame X    | K-Frame X chassis using V16.2.2 (Linux) doesn't see external power supplies 1 and 2.   | KFCK-27191 | 00833102 |

#### **Software Issues Resolved in Release 16.2.3**

| Area                     | Issues  | ID         | Case ID              |
|--------------------------|---|------------|----------------------|
| iDPM:<br>K-Frame XP      | iDPM sometimes flashes on call to on-air. Keyer Delay didn't cover flash.   | KFCK-27189 |                      |
| iDPM:<br>K-Frame XP      | Some configurations of cascading iDPM and eDPM can cause flashing.  | KFCK-27171 | 00829480             |
| IP I/O:<br>K-Frame X, XP | RxErrorCount and TxErrorCount on occasion shows erroneous large numbers.  | KFCK-27190 |                      |
| IP I/O:<br>K-Frame XP    | Color space information is not always passed on correctly via ST 2110-40 ancillary data. May cause a color shift. | KFCK-27044 | 00821011<br>00831695 |

#### **Software Issues Resolved in Release 16.2.2**

| Area         | Issues  | ID         | Case ID  |
|--------------|---|------------|----------|
| Macros:      | A replace attach macro in some instances can        | KFCK-26781 | 00803299 |
| KAYN Panel   | temporarily disable the source selection buttons to |            |          |
|              | the right of it on that bus.                        |            |          |
| IP I/O:      | ST 2110-40 VPID data incorrect - it does not appear | KFCK-27187 | 00808712 |
| K-Frame X    | to match what is configured in the User             |            |          |
|              | Setups>Suite Prefs>Suite Resources>Suite Signal     |            |          |
|              | Type menu.  |            |          |
| Transition   | The Korona Transition module touchscreen needs to   | KFCK-27139 |          |
| Module:      | support new TFT display.                            |            |          |
| Korona Panel |   |            |          |
| IP I/O:      | ST 2210-40 VPID data incorrect - does not appear to | KFCK-27057 | 00808712 |
| K-Frame X    | match what is configured in the User Setups > Suite |            |          |
|              | Prefs > Suite Resources > Suite Signal Type menu.   |            |          |
|              | Fixed for XP in V16.0.0 release.                    |            |          |
| SDI I/O:     | In FOM 1080p-A, SDI output is sending VPID info out | KFCK-27067 | 00824061 |
| K-Frame X    | a second time on Line 572.                          |            |          |

## **Software Issues Resolved in Release 16.2.1**

| Area                           | Issues   | ID         | Case ID  |
|--------------------------------|--|------------|----------|
| Macros:<br>Bus Linking         | Bus Linking Macros that create bus links are not translated from software before V16.0.0                                       | KFCK-27137 |          |
| IS-04 & IS-05:<br>K-Frame X/XP | Some of the IS-05 Sender and Receiver constraints are missing, causing problems with some software defined network situations. | KFCK-27063 | 00822968 |
| DPM:<br>K-Frame X              | FPGA timing adjustment for DPM on some versions of the ME board. Only seen in V16.2.0.   | KFCK-27136 |          |

## **Software Issues Resolved in Release 16.2.0**

| Area                                   | Issues  | ID         | Case ID  |
|--|---|------------|--|
| Menu:                                  | Over time, the Menu may occasionally begin to slow down, miss information, and the memory usage may go very high.   | KFCK-27061 | 00800357   |
| System:<br>K-Frame X                   | There are rare instances where the CPL subsystem may cause the frame to reboot.   | KFCK-26853 | 00810493   |
| NMOS:<br>K-Frame X                     | NMOS has inconsistent NMOS label - Issue fixed in previous version of K-Frame X.  | KFCK-26593 | 00793058   |
| NMOS:<br>K-Frame XP                    | NMOS V1.2 is missing V16.1.3. Can see the IP I/O board but no TX and RX devices.  | KFCK-27050 | 00819587   |
| IP I/O:<br>K-Frame XP                  | Timing of the video inputs on -01 version of IP I/O boards may occasionally drift and delay the video essence. The delay may build up to multiple frames.           | KFCK-26794 | 00804571   |
| IP I/O:<br>K-Frame X                   | The -01 version of the IP I/O board may have some video inputs drift over time resulting in multiple frames of delay. Fix for the K-Frame XP in a previous release. | KFCK-26789 | 00790656<br>00801847<br>00804356<br>00808488<br>00808954 |
| Format<br>Conversion IO:<br>K-Frame XP | Conversion from 2160p to 1080p and back to 2160p needs improved.  | KFCK-27060 |  |
| Gearbox I/O:<br>K-Frame X/XP           | MatchSync not working in SD modes   | KFCK-27058 |  |
| VDCP Serial:<br>K-Frame X/XP           | May not always connect/re-connect during boot or reboot.  | KFCK-27059 |  |
| iDPM:<br>K-Frame XP                    | Splits and Mirrors modifier "Double Image" does not work correctly. The image may become distorted.   | KFCK-27039 |  |

#### **Software Issues Resolved in Release 16.1.4**

| Area                                 | Issues   | ID         | Case ID              |
|--------------------------------------|--|------------|----------------------|
| GFX Interface:<br>K-Frame XP         | configured and the device is disabled, the switcher may lock up.   | KFCK-26599 | 00800357             |
| GFX Device<br>Control:<br>K-Frame XP | In some GFX Device configurations, switchers with IP boards may require significantly longer than normal time to boot/reboot.  | KFCK-26809 | 00806155             |
| iDPM:<br>K-Frame XP                  | In FOM 2160p, the certain positions of the Warps:<br>Splits and Mirrors, can cause video noise distortion<br>of the warped image at some levels of separation.           | KFCK-26940 | 00819535             |
| iDPM:<br>K-Frame XP                  | Where the drop shadow comes into contact with the bottom line of the screen with 2160, the background comes through. The problem occurs on the right edge of the screen. | KFCK-27038 |                      |
| All boards:<br>K-Frame XP            | Video down-converted from 2160p > 1080p on the output board may occasionally flash when the video goes through certain paths in the switcher.                            | KFCK-27037 |                      |
| iDPM:<br>K-Frame XP                  | Intermittent shaking video in iDPM and eDPM. May go away with frame reboot and not return until next reboot.   | KFCK-27040 | 00817509<br>00819394 |

#### **Software Issues Resolved in Release 16.1.3**

| Area                      | Issues  | ID         | Case ID  |
|---------------------------|---|------------|----------|
| Controller:<br>K-Frame XP | In a few specific configurations and conditions, an error in the Controller Hardware Address Decoder (HAD) can cause the intermittent loss of output packets which will be detected as RTP sequence errors on the output video. | KFCK-26912 | 00814326 |

#### **Software Issues Resolved in Release 16.1.2**

| Area                            | Issues  | ID         | Case ID |
|---------------------------------|---|------------|---------|
| Kayenne<br>Panel:<br>K-Frame XP | The Kayenne Control Panel will not operate correctly due to missing files from the installer in V16.1.1 release. No other Panels were affected. | KFCK-26914 |         |

## **Software Issues Resolved in Release 16.1.1**

| Area                         | Issues   | ID         | Case ID  |
|------------------------------|--|------------|----------|
| IP I/O Boards:<br>K-Frame XP | Some inputs from a LiveTouch server may have noise on PGM, PVW, or AUX.  | KFCK-26871 | 00811427 |
| IP I/O Boards:<br>K-Frame XP | The IP Output may have 10ms RTP offset in 12G Mode.  | KFCK-26862 | 00812750 |
| IP I/O Boards:<br>K-Frame XP | The clock for SFP 1 is shared with the other SFPs on<br>the same IP I/O Board. If the signal to SFP 1 is lost<br>(connection to switch lost, SFP unplugged, etc.),<br>this may affect the other SFPs on the same board,<br>including the redundant SFPs. | KFCK-26843 | 00804684 |

#### **Software Issues Resolved in Release 16.1.0**

| Area                                       | Issues   | ID         | Case ID |
|--|--|------------|---------|
| File System:<br>Panel Prefs:<br>K-Frame XP | Legal null references in some Panel Preference Files, can cause errors on loading. | KFCK-26845 |         |

#### **Software Issues Resolved in Release 16.0.4**

| Area                         | Issues  | ID         | Case ID  |
|------------------------------|---|------------|----------|
| IS-04 & IS-05:<br>K-Frame XP | Boards register with interface of and href of 0.0.0.0 | KFCK-26804 | 00808400 |

#### **Software Issues Resolved in Release 16.0.3**

| Area           | Issues                                      | ID         | Case ID |
|----------------|---|------------|---------|
| GearBox and    | Switcher needs to recognize new versions of | KFCK-26786 |         |
| ConvIO boards: | GearBox and ConvIO boards.                  |            |         |
| K-Frame XP     |   |            |         |

## **Software Issues Resolved in Release 16.0.2**

<INTERNAL RELEASE>

#### **Software Issues Resolved in Release 16.0.1**

| Area  | Issues  | ID         | Case ID |
|---|---|------------|---------|
| Key Store:<br>K-Frame XP                      | Key Store Keyer Cutout Source has corrupted video/memory.                       | KFCK-26627 |         |
| IS-04 & IS-05:<br>IP I/O Boards<br>K-Frame XP | IP Boards occasionally publish the Secondary URL even though using Primary SFP. | KFCK-26785 |         |
| Power<br>Monitoring:<br>K-Frame XP            | Sometimes the four power supply's reporting is incorrect.                       | KFCK-26626 |         |

## **Software Issues Resolved in Release 16.0.0**

| Area                                   | Issues   | ID         | Case ID  |
|--|--|------------|----------|
| IP IO Boards:<br>K-Frame XP            | IP at edge of horizontal timing veryintermittently offsets video to left.  | KFCK-26607 |          |
| IP IO Boards:<br>K-Frame XP            | Inputs on the -01 version of IP I/O Boards will occasionally delay the video essence for multiple frames.                      | KFCK-26794 | 00804571 |
| Hot Swap:<br>K-Frame XP                | Changing I/O Board Type with Hot Swapmay require frame reset to work.  | KFCK-26608 |          |
| IP IO Boards: K-<br>Frame XP           | SDP file of Senders always says SDR andcolor space undefined.  | KFCK-25927 | 00766459 |
| Format<br>Conversion IO:<br>K-Frame XP | Media Port on Conversion I/O board doesnot always initialize correctly.  | KFCK-26609 |          |
| Format<br>Conversion IO:<br>K-Frame XP | In the FOM of 720p, the input on the Format Conversion card drops the videoby a line when MatchSync is applied.                | KFCK-26610 |          |
| Image Store: K-<br>Frame XP            | On rare occasions, the Frame Crasheswhen Image Store Restore is enabled  | KFCK-26611 |          |
| Image Store:K-<br>Frame XP             | Image Store Import of AVI and TGA inFOM 2160p may get an OutOfMemoryException error and silently fail.                         | KFCK-26612 |          |
| Image Store:K-<br>Frame XP             | In FOM of 1080i, the Image Store appears to be recording F1:F2 with one field delayed  | KFCK-26037 |          |
| Image Store:K-<br>Frame XP             | On rare occasions, the Image Store Import will fail without an error message and import will not work until the menu is reset. | KFCK-25523 |          |
| Image Store:K-<br>Frame XP             | Canceling an Image Store save or importoperation might not clean up the file directories correctly.                            | KFCK-25530 |          |
| System:<br>K-Frame XP                  | Does not pass Active Format Descriptor   | KFCK-26137 | 00786893 |
| iDPM:<br>K-Frame XP                    | Garbage in picture with ExtremePerspective in 2160p FOM.   | KFCK-26613 |          |
| iDPM:<br>K-Frame XP                    | In FOM of 720p, iDPMs are shifted up aline.  | KFCK-26614 |          |
| Film Look:<br>K-Frame XP               | The Film Look parameters to not workcorrectly in some value ranges.  | KFCK-26588 | 00798804 |
| 2DPM:<br>K-Frame XP                    | 2DPM Border line between video andborder when Z rotate is used.  | KFCK-26615 |          |
| IP IO Boards:<br>K-Frame XP            | IP at edge of horizontal timing veryintermittently offsets video to left.  | KFCK-26607 |          |

Software Issues Resolved in Release 16.0.0 (continued...)

| Timing<br>Analyzer: | Timing Analyzer should be more specific (59.94 not 59.94/60) | KFCK-26616  |          |
|---------------------|--|-------------|----------|
| K-Frame XP          | 1100 37.747 00)  |             |          |
|                     | When in 2160n FOM Chroma Koy Auto Cotup                      | KFCK-26617  |          |
| Chroma Key: K-      | When in 2160p FOM, Chroma Key Auto Setup                     | KFCK-20017  |          |
| Frame XP            | Cursor start at bottom of screen and is oval.                |             |          |
| PCU:                | On rare occasions, the PCU Configuration Alt IP              | KFCK-26620  |          |
| K-Frame XP          | stripe selection are not displayed correctly.                |             |          |
| SNMP:               | Snmpwalk - vsmNetworkConfig may fail                         | KFCK-26621  |          |
| K-Frame XP          |  |             |          |
| SNMP:               | SNMP GetBulk doesn't always work.                            | KFCK-26622  |          |
| K-Frame XP          | •  |             | _        |
| Editor Port: K-     | Editor Source Mapping Menu does not allow for                | KFCK-26619  |          |
| Frame XP            | mapping sources.   |             | _        |
| Multiviewer: K-     | In 720P and in the Quad Layout, the video in the             | KFCK-26618  |          |
| Frame XP            | Multiviewer has an offset                                    |             | _        |
| Wipes Menu: K-      | When changing wipe patterns on PGM ME the                    | KFCK-26150  | 00793477 |
| Frame XP            | menu does not always update to show the wipe                 |             |          |
|                     | pattern selected, but on ME1 it does.                        |             |          |
| Panel / Menu /      | The panel, frame, and menu would work better                 | Enhancement |          |
| Frame Comm:         | over longer IP connections using TCP/IP instead of           |             |          |
| K-Frame XP          | RDP over UDP/IP.   |             |          |
|                     |  |             | L        |

#### **Software Issues Resolved in Release 15.3.3**

| Area                | Issues  | ID         | Case ID  |
|---------------------|---|------------|----------|
| Menu:<br>K-Frame XP | Wipes & Mattes > Patterns Menu can be non-<br>responsive.  WORKAROUND: Select ME 1-4 and PGM/PST point<br>of use on menu, then use the menu normally. | KFCK-26587 | 00797335 |

## **Software Issues Resolved in Release 15.3.2**

| Area                                | Issues  | ID         | Case ID  |
|-------------------------------------|---|------------|----------|
| Devices:<br>K-Frame XP              | Switcher is not communicating with AvidFast Serve DDR's via VDCP Ethernet.                          | KFCK-26121 | 00784289 |
| PTP:<br>K-Frame XP                  | Management response packet causesproblems on other interfaces. Response Packet size may be invalid. | KFCK-26022 | 00780982 |
| Editor<br>Interface: K-<br>Frame XP | Editor interface doesn't work.  | KFCK-26143 | 00790328 |

## **Software Issues Resolved in Release 15.3.1**

| Area                         | Issues   | ID          | Case ID  |
|------------------------------|--|-------------|----------|
| IS-04 & IS-05:<br>K-Frame XP | NMOS control redundancy doesn't workcorrectly.   | KFCK-26138  | 00788449 |
| IS-04 & IS-05:<br>K-Frame XP | NMOS communications disconnects from server in some configurations using static routes.  | KFCK-26131  | 00780988 |
| IP IO Boards:<br>K-Frame XP  | The Switcher rejects SDP files and audiowith a=ptime:0.12 instead of a=prime:0.0125 (As done by LAWO control systems)                  | KFCK-26132  |          |
| IP IO Boards:<br>K-Frame XP  | 2110-30 Audio is distorted in some configurations.   | KFCK-26126  | 00785650 |
| IS-04 & IS-05:<br>K-Frame XP | Need Static Routes for fail over connection to<br>Global Registry. (Need change to Eng Setup > Node<br>Settings > NMOS Configurations) | Enhancement | 00770425 |
| Image Store:<br>K-Frame XP   | Four channels of Audio now works correctly. Record/Play Import & Export  | Enhancement |          |

## **Software Issues Resolved in Release 15.3.0**

| Area  | Issues   | ID         | Case ID |
|---|--|------------|---------|
| Frame<br>Simulator:<br>K-Frame XP             | Default I/O Boards in K-Frame XP Frame Simulator are wrong.  | KFCK-26025 |         |
| GearBox IO<br>Board:<br>K-Frame XP            | Timing Analyzer is sometimes getting information from the wrong GearBox Inputs.  | KFCK-26034 |         |
| Image Store:<br>K-Frame XP                    | Movies in 2160p will save as .EIF files if they have been edited. It appears that if you trim the front and back of a movie thatit will save with a .EIF extension rather than a .ISF.  This doesn't cause a problem for the K- Frame XP but may cause a problem for theother K-Frame systems. | KFCK-26036 |         |
| GearBox IO<br>Board:<br>K-Frame XP            | Timing Analyzer is sometimes getting information from the wrong GearBox Inputs.  | KFCK-26034 |         |
| IP I/O Boards:<br>K-Frame XP                  | Changing Audio Stream Format doesn't always change "A" side.   | KFCK-26027 |         |
| IP I/O Boards:<br>K-Frame XP                  | B Side IP Audio occasionally had configuration issues.   | KFCK-26029 |         |
| IP I/O Boards:<br>K-Frame XP                  | Payload Type for Audio goes to "98" when you use "dot enter"   | KFCK-26026 |         |
| IP I/O Boards<br>Menu:<br>K-Frame XP          | 8x4 IP I/O Boards do not show System Input/Output names in I/O Config Menu   | KFCK-26031 |         |
| IP I/O Boards<br>Configuration:<br>K-Frame XP | "Restore Defaults" on Port Config SFPs menu can cause a loss of input video until the frame is reset.  | KFCK-25924 |         |
| IP Video:<br>KFrame XP                        | When GVO and/or Cisco Switches ping the Media LAN of XP Switcher it is inconsistent and pings may fail to Connect.   | KFCK-25989 |         |
| IS-04/IS-05:<br>K-Frame XP                    | IP node has duplicated NMOS Node IDs that can be caused by swapping boards.  | KFCK-26001 |         |
| Multiviewer: K-<br>Frame XP                   | There may be a dark flash at the top of the multiviewer video when Tally or Tiles are updated.   | KFCK-25922 |         |
| Image Store:<br>K-Frame XP                    | Image Store - Loading stills and movies of one resolution while FOM is a different resolution may corrupt the cache.   | KFCK-25912 |         |
| Image Store:<br>K-Frame XP                    | Image Store Loading ID's is loading slower in some circumstances.  | KFCK-25520 |         |
| Input Timing:<br>K-Frame XP                   | The Input Timing Analyzer is not always correct for some IO Boards.  | KFCK-25922 |         |
| IP I/O Boards:<br>K-Frame XP                  | Redundant Audio is not working when route is made from NMOS.   | KFCK-26032 |         |
| IP I/O Boards:<br>K-Frame XP                  | Ethernet Ports reporting Link/Lock Up when no SFP connected.   | KFCK-26035 |         |
| Frame<br>Simulator:<br>K-Frame XP             | Default I/O Boards in K-Frame XP Frame Simulator are wrong.  | KFCK-26025 |         |
| SNMP:<br>K-Frame XP                           | Default IP Addresses and Community name are not correct for SNMP values for the frame.   | KFCK-9209  |         |
| System:<br>K-Frame XP                         | System may erroneously report Power Supply status as present but Failed.   | KFCK-26038 |         |

#### Software Issues Resolved in Release 15.3.0 continued...

| Area                              | Issues   | ID         | Case ID |
|-----------------------------------|--|------------|---------|
| System:<br>K-Frame XP             | ME and Aux timing isn't always being setcorrectly on Power Cycle.                            | KFCK-26028 |         |
| System Timing:<br>K-Frame XP      | H&V Phase calcs don't recalculate after2160p FOM change.                                     | KFCK-26039 |         |
| Timing<br>Analyzer:<br>K-Frame XP | The Indications for the 2160p inputvideo are incorrect.                                      | KFCK-25910 |         |
| Timing<br>Analyzer:<br>K-Frame XP | Timing Analyzer green bar is calculating status wrong for uSec adjustments atedge of timing. | KFCK-26030 |         |
| Timing<br>Analyzer:<br>K-Frame XP | Timing Analyzer occasionally displaying the wrong information.                               | KFCK-26040 |         |

#### **Software Issues Resolved in Release 15.2.0**

<INTERNAL RELEASE>

#### **Software Issues Resolved in Release 15.1.1**

| Area          | Issues   | ID          | Case ID  |
|---------------|--|-------------|----------|
| 2DPM          | Moving 2DPM off-screen or shrinking to zero size should not tally as on-air. | KFCK-25527  |          |
| ID I/O Deemde |  | Fubanaana   |          |
| IP I/O Board: | Modify Stream Health Monitoring to Log changes                               | Enhancement |          |
| K-Frame XP    | between Stream Present / NotPresent.   |             |          |
| IP I/O Board: | If the I/O card sees a DHCP message, it may zero                             | KFCK-25951  |          |
| K-Frame XP    | out some IP configuration data, stopping the video                           |             |          |
|               | stream Present / Not Present.  |             |          |
| IP I/O Board: | SFP may occasionally drop link in 4 x 2 mode causing                         | KFCK-25552  | 00761912 |
| K-Frame XP    | the output stream to belost.   |             |          |

## **Software Issues Resolved in Release 15.1.0**

| Area                                    | Issues  | ID          | Case ID  |
|---|---|-------------|----------|
| Camera Tally:<br>K-Frame XP             | Camera Tally via XML Camera Protocol may not work for cameras without a basestation or CCU. (This includes the LDX 100) | KFCK-24271  | 00723412 |
| E-MEM:<br>K-Frame XP                    | The frame is giving next register instead of the next empty register to LEARN DOT. command for some register ranges.    | KFCK-25911  |          |
| E-MEM &<br>Timeline Menu                | E-MEM & Timeline > Timeline Edit > E-MEM enables Keyers 5 and 6 Not Visible.  | KFCK-25926  |          |
| Frame Operating<br>Mode:<br>K-Frame XP  | 1080p23.98, 2160p23.98, 1080p29.97, or 2160p29.97 may not be configuredcorrectly on boot.                               | KFCK-25533  |          |
| IP I/O Board:<br>K-Frame XP             | Added Output Gearbox functionality (1080p <> 2160p)   | Enhancement |          |
| IS-04 & IS-05:<br>K-Frame XP            | Need the ability to configure the Node JARVersion to V1.2 instead of V1.3 in the console.                               | Enhancement |          |
| Multiviewer &<br>ME View:<br>K-Frame XP | Need Multiviewer and ME View Features enabled.  | Enhancement |          |
| Panel Memory:<br>K-Frame XP             | Panel Memory is not always being recalled from disk correctly in show loads orindividually.                             | KFCK-25923  |          |
| Signal Integrity:K-<br>Frame XP         | Occasional minor bit errors on some signalpaths.  | KFCK-25914  |          |

#### **Known Issues**

| Area                                | Issues   | ID         | Case ID  |
|-------------------------------------|--|------------|----------|
| NMOS Registry IPs                   | NMOS access to the IO cards can be affected<br>by invalid IP addresses in the registry. To clear<br>these invalid IP addresses, navigate on the<br>MENU to find the invalid IP address and press<br>'.' to clear the invalid IP address.   | KFCK-27316 | 00847772 |
| Clip Store                          | Using a Macro to stop a ClipStore recordingleaves the channel in record mode. Stoppingthe recording by pressing the menu Stop button works correctly. Workaround: Do not use Macros to stop arecording or if you do, toggle the RecordEnable button to get back into play mode.    |            |          |
| Control Panel                       | On a few systems, when the Control Panel is reset, the video may perform a transition and the video may randomly cut to what ison the preview bus.   | KFCK-21481 | 00604179 |
| Device Control                      | Devices at frame rates slower than 25Hz maynot be controlled correctly.  | KFCK-25543 |          |
| Device Control                      | Sometimes after a reset of the frame, noneof the devices (except the ClipStore) are enabled in suite 2. They can be enabled manually.  | KFCK-24235 |          |
| DPM:<br>K-Frame XP                  | iDPM with narrow borders, borders may disappear at certain edge rotations: WORKAROUND: Slightly increase the sizeof the border.  | KFCK-26042 |          |
| E-MEM                               | Circular sequencing of registers is not supported.   | KFCK-9965  |          |
| Editor Interface                    | The first time an Editor Port is assigned, enabled and connected, it may not start correctly.  WORKAROUND: If the Editor Port is configured to the desired state and does notwork the first time, reset the Frame and Menu and enter the Editor Port configurations a second time. | KFCK-21673 |          |
| Format<br>Conversion:<br>K-Frame XP | When FOM 2160p and using the output to adjust the vertical offset of 2160p it doesn't work in the positive direction. FOM 2160 conversion to other frame rates vertical offset works correctly.  |            |          |
| GV Korona<br>Control Panel          | User Setup > Panel Prefs > Panel User Interactions > OLED brightness soft knob adjustment is not linear. If you are at 100% and take the brightness to 10%, youdon't see the change until you turn the knob up again.  |            |          |
| GV KoronaMenu                       | GV Korona menu brightness doesn't work inUser<br>Setups > Panel Prefs > Panel User Interactions.<br>WORKAROUND: Set the menu brightnessusing<br>Windows adjustments.   | KFCK-19509 |          |
| Hot Swap                            | During the hot swap of a Frame board, if another board is removed and replaced, the removal of the second board is not detected. WORKAROUND: Wait ten seconds betweenhot swapping boards.  | KFCK-17208 |          |
| Image Store                         | After recording a movie, the blue progress bar may be blank until the movie is saved tocache.  | KFCK-18178 |          |

## Known Issues continued...

| Area                | Issues   | ID          | Case ID  |
|---------------------|--|-------------|----------|
| IO Config Menu:     | If the menu application is started before the frame,   | KFCK-26839  |          |
| io coming meria.    | the Eng Setup > Video I/O > I/O Config Menu may  | KI CK 2005) |          |
|                     | occasionally come up blank. The menu application   |             |          |
|                     | must be restarted for the I/O Config menu to work  |             |          |
|                     | correctly.   |             |          |
| IP I/O Board        | Hot swap of IP I/O board may affect adjacentIP I/O Board.  | KFCK-25542  |          |
| IP I/O Board        | It takes over 30 seconds to change SFP Speed on IP cards; it will flash twice after thechange is made. | KFCK-25182  |          |
| IP I/O Board:       | On some occasions, the IP i/O board may take as long   | KFCK-24378  |          |
| GV K-Frame X        | as six minutes to power up froma complete powered  |             |          |
| GV K-Frame V        | off state.   |             |          |
| IP I/O Board:       | On rare occasion with some Cisco networkswitches   | KFCK-24858  |          |
| GV K-Frame X        | with QSFP, after a boot, the input video may be pink   |             |          |
|                     | or green.  |             |          |
|                     | WORKAROUND: Reset the QSFP in the Cisco network switch.  |             |          |
| Karrera Control     | DPOP of USER buttons does not work if SplitME and  | KFCK-9332   |          |
| Panel               | PRI/SEC are selected.  |             |          |
| Karrera Control     | Panel Memory on the Karrera does not record the  | KFCK-8249   |          |
| Panel Memory        | page offsets of the Macro Mode inthe Local E-MEM section.  |             |          |
| Kayenne             | Machine Control Module only works fromSuite 1  | KFCK-9933   |          |
| Control             | Surface A and/or Suite 2 Surface A.  | /DE364      |          |
| Panel/Machine       |  |             |          |
| Machine             | Enabled devices that are not connected, willcontinue   | KFCK-9101   |          |
| Control             | to try and connect which can cause menu slow-  | /DE1228     |          |
|                     | downs.   |             |          |
| Magra               | WORKAROUND: Disable unused devices.  | KFCK-8505   | 00487254 |
| Macro<br>Edit/Build | Starting to edit or saving a macro may be delayed during a file operation in either suite.             | /DE1831     | 00467234 |
| Media PortInput     |  | KFCK-25170  |          |
| media i oi ciriput  | video is connected.  | KI CK 25170 |          |
| Menu Software       | Immediately after the installation of new software, the  | KFCK-19611  |          |
| Installation        | Status Menu reports the previous version of the  |             |          |
|                     | software even after asuccessful update.  |             |          |
|                     | WORKAROUND: Restarting the Menucorrects the  |             |          |
|                     | issue.   |             |          |
| Node Settings       | Joy Stick Override mapped to "None" stillselects source.   |             |          |
|                     | D 15 TCD 11 11   | 9953/DE344  |          |
| Panel:              | Panel Frame TCP connection may not always notify user  | KFCK-26841  |          |
|                     | if Ethernet is disconnected. Communications will recover   |             |          |
| PTP:                | when Ethernet cable is reconnected.  Loss of the PTP messages might not bereported                     | KFCK-25181  |          |
| K-Frame X           | since the Flywheel Reference onthe PTP Board is  | KI CK-25101 |          |
| K I Tallie X        | providing a valid reference that had been synchronous  |             |          |
|                     | with the PTP Master Clock.   |             |          |
| System Timing       | Sometimes internal sources are incorrectly reported  | KFCK-24868  | 00695116 |
| j                   | as out of time.  |             |          |
| Timing              | Color visual indicator missing on Redundant inputs.  | KFCK-25545  |          |
| Analyzer            |  |             |          |



#### **Grass Valley Technical Support**

For technical assistance, contact our international support center, at 1-800-547-8949 (US and Canada) or +1 530 478 4148.

To obtain a local phone number for the support center nearest you, please consult the Contact Us section of Grass Valley's website (www.grassvalley.com).

An online form for e-mail contact is also available from the website.

#### **Corporate Head Office**

Grass Valley 3499 Douglas-B.-Floreani St-Laurent, Quebec H4S 2C6 Canada

Telephone: +1 514 333 1772 Fax: +1 514 333 9828

www.grassvalley.com