

M-Series iVDR Version 2.0.10 Release Notes and Installation Instructions

Table of Contents

Grass Valley Product Support.....2
Version 2.0.10 new features and introductions.....3
Operational considerations.....4
Installing software version 2.0.10.....6
Known issues.....12

IMPORTANT: VGA Display ‘hot-key’ sequence

To set the correct display settings on systems without the optional front panel, press the Ctrl+Alt+C hot-key sequence after AppCenter initializes. Refer to “VGA monitor display settings” on page 12.

Copyright © 2005 Thomson Broadcast and Media Solutions, Inc. All rights reserved. Printed in the United States of America.

This document may not be copied in whole or in part, or otherwise reproduced except as specifically permitted under U.S. copyright law, without the prior written consent of Thomson Broadcast and Media Solutions, Inc., P.O. Box 59900, Nevada City, California 95959-7900

Grass Valley, M-Series, Profile, and Profile XP are either registered trademarks or trademarks of Thomson Broadcast and Media Solutions, Inc. in the United States and/or other countries. Other trademarks used in this document are either registered trademarks or trademarks of the manufacturers or vendors of the associated products. Thomson Broadcast and Media Solutions, Inc. products are covered by U.S. and foreign patents, issued and pending. Additional information regarding Thomson Broadcast and Media Solutions, Inc.'s trademarks and other proprietary rights may be found at www.thomsongrassvalley.com.

Product options and specifications subject to change without notice. The information in this manual is furnished for informational use only, is subject to change without notice, and should not be construed as a commitment by Thomson Broadcast and Media Solutions, Inc. Thomson Broadcast and Media Solutions, Inc. assumes no responsibility or liability for any errors or inaccuracies that may appear in this publication.

Grass Valley Product Support

To get technical assistance, check on the status of a question, or to report new issue, contact Grass Valley Product Support via e-mail, the Web, or by phone or fax.

Web Technical Support

To access support information on the Web, visit the product support Web page on the Grass Valley Web site. You can download software or find solutions to problems by searching our Frequently Asked Questions (FAQ) database.

World Wide Web: <http://www.thomsongrassvalley.com/support/>

Technical Support E-mail Address: gvgtechsupport@thomson.net.

Phone Support

Use the following information to contact product support by phone during business hours. Afterhours phone support is available for warranty and contract customers.

United States	(800) 547-8949 (Toll Free)	France	+33 (1) 34 20 77 77
Latin America	(800) 547-8949 (Toll Free)	Germany	+49 6155 870 606
Eastern Europe	+49 6155 870 606	Greece	+33 (1) 34 20 77 77
Southern Europe	+33 (1) 34 20 77 77	Hong Kong	+852 2531 3058
Middle East	+33 (1) 34 20 77 77	Italy	+39 06 8720351
Australia	+61 1300 721 495	Netherlands	+31 35 6238421
Belgium	+32 2 3349031	Poland	+49 6155 870 606
Brazil	+55 11 5509 3440	Russia	+49 6155 870 606
Canada	(800) 547-8949 (Toll Free)	Singapore	+656379 1390
China	+86 106615 9450	Spain	+ 34 91 512 03 50
Denmark	+45 45968800	Sweden	+46 87680705
Dubai	+ 971 4 299 64 40	Switzerland	+41 (1) 487 80 02
Finland	+35 9 68284600	UK	+44 870 903 2022

Authorized Support Representative

A local authorized support representative may be available in your country. To locate the support representative for your country, visit the product support Web page on the Grass Valley Web site.

Version 2.0.10 new features and introductions

Version 2.0.10 includes performance improvements and support for all M-Series iVDR models. Features and performance improvements introduced by previous releases are also included in version 2.0.10. To learn about past releases, refer to the following section “[What’s new by version](#)”.

New in this release:

- Support for 300GB disk drives
- Improved recovery behavior for interrupted video sources

Refer to the 2.0 version of the *M-Series User Manual* for information on the features introduced by this and all past software release. You can access all M-Series iVDR documentation at <http://www.thomsongrassvalley.com/support/>.

What’s new by version

Version 2.0.10 includes all features and performance improvements introduced by previous releases. The following sections describe the introductions included in recent past releases.

Version 2.0.9

Version 2.0.9 introduced the following hardware features to extend the capabilities of the M-Series iVDR.

- Support for models M-122A and M-222A
- Support for the IEEE 1394 Interface option on the M-122A and M-222A

Version 2.0.4

Version 2.0.4 introduced the following hardware features to extend the capabilities of the M-Series iVDR.

- Digital audio I/O— ES/EBU and SDI embedded, 4ch/video on the M-222D.
- 50Mbs video compression—DV50, and MPEG-2 I Frame only, along with the new digital audio I/O—AES/EBU and SDI embedded, 4ch/video on the M-322D.
- Introduced the IEEE 1394 option on the M-222D and M-322D.

NOTE: Version 2.0.4 did not support models M-122A or M-222A.

Version 1.6.9

- Erase unused media feature
- Remote control through GPI Inputs
- Controlling external equipment through GPI Outputs
- BVW protocol
- Continuous record mode
- Cue points

- Keyboard shortcuts
- Variable Speed Play enhancements
- Append record using serial protocol control
- Repositioning the AppCenter window
- NewsQ Pro support via the AMP protocol.

Version 1.5.12

- Saving a playlist as a program
- Transferring playlists and programs
- Saving clip and event audio levels
- Advanced Search
- Freeze on next event
- Configuration dialog box enhancements

Operational considerations

Use the following information in your operational planning for the iVDR.

Minimum record to playback time

The Player application enforces a 5 second minimum record to play time when playing a clip that is still being recorded. To play a clip that is still recording, start record, then wait at least 5 seconds before starting playback.

Composite analog video input performance

The iVDR can record signals from most non-timebase corrected signal sources such as color under video playback devices, i.e. VHS or U-Matic VTRs, and low cost cameras. However, for reliable recording performance some devices may require external signal conditioning products, i.e. timebase correction.

Remote control protocol support

You can use remote control devices and automation software developed for the M-Series iVDR that use industry-standard serial protocols. For each supported protocol, the iVDR provides a protocol-specific application. Be sure to contact your 3rd party automation system or software provider to ensure that the iVDR is supported. Contact your Thomson Grass Valley sales representative for a list of companies that provide certified applications for the M-Series iVDR.

Recording using BVW protocol

To record using BVW protocol, you must manually load a new clip in BVW Recorder before the record channel can respond to the start record command. The BVW Recorder must be in “Local and Protocol control mode” to allow you to create the new

clip locally. If the recording is stopped, you must eject the current clip, and then create a new clip since BVW Recorder does not support append record. Refer to the *M-Series User Manual* for detailed operating instructions.

Using USB devices

The USB connectors on the rear panel and front panel can be used to connect a USB drive, mouse, keyboard, or other USB device. Do not plug or unplug these devices while the iVDR is being used for critical play to air activity.

Verifying clip transfer rate before playing

Before playing a clip that is being imported from a file or stream, verify that the clip transfer rate is higher than the clip data rate using the Transfer Monitor. This is required to ensure uninterrupted playback.

Playing lists containing GPI output triggers

You can assign GPI output triggers to events and sections in a playlist. The GPI outputs can be used to trigger external equipment when the list plays. Before you can use GPI output triggers in a list, you must assign GPI outputs to the play channel using Configuration Manager. If you want to play a list that was created on another play channel, you must ensure that GPI triggers assigned to the play channels use the same names, otherwise the GPI triggers will not occur.

Virus software support

Thomson Grass Valley does not recommend installing third party software on your iVDR. However, if you must install virus scanning software, configure it for manual virus scan only. Automatic virus scanning could disrupt iVDR operation and should not be used.

Continuous record program length

A continuous recording is stored in the iVDR as a program. When the program is stored, its duration will be 3 minutes longer than the continuous record length specified. Take this into consideration when operating the iVDR with the media disks nearly full.

NetCentral SNMP Agent

This software release installs the M-Series NetCentral SNMP Agent, however, the agent must be unlocked for operation with NetCentral Manager software. NetCentral Manager provides centralized monitoring using Simple Network Management Protocol (SNMP). The M-Series SNMP agent allows the M-Series to collect and store management information (such as disk errors, temperature, video and audio status) and make this available to NetCentral Manager. Contact your Thomson Grass Valley representative for more information about obtaining a software key to unlock the M-Series SNMP agent and configuring it for use with NetCentral Manager.

Installing software version 2.0.10

M-Series iVDR system software version 2.0.10 was installed on your new iVDR at the factory. In normal operation, you do not need to reinstall system software.

Perform the following installation procedure if:

- You are updating the iVDR system software.
- You are instructed by Thomson Grass Valley product support to re-install system software.

This software installation procedure includes:

- [Part 1: “Install “Critical” Windows updates \(recommended\)”](#)
- [Part 2: “Special procedures if updating from 1.5.x or 1.6.x”](#)
- [Part 3: “Update the M-Series media file system”](#)
- [Part 4: “Install M-Series system software”](#)
- [Part 5: “Create a system disk image file”](#)

Part 1: Install “Critical” Windows updates (recommended)

Windows “Critical Updates and Service Packs” are recommended, but not required for version 2.0.10. The iVDR must be connected to the internet to perform this procedure. If the iVDR does not have internet access, skip this procedure and proceed to [Part 2: on page 8](#).



CAUTION: Only “Critical Updates and Service Packs” should be installed. Do not install other Windows 2000 or driver updates on your iVDR.


From the factory, Automatic Windows Updates are disabled. This prevents updates from being performed in a manner that could harm the operation of networked iVDRs. Do not modify the Automatic Update setting.

Start the iVDR in Windows Safe Mode

Starting the iVDR in safe mode prevents the update program from using the media drives as the target for downloading and installing windows updates.

To start Windows in safe mode:

1. Connect a keyboard and mouse to the iVDR rear panel or front panel.
You’ll need these to boot in Safe mode and use Windows Update program.
2. Restart the iVDR (and Windows) as follows:
 - a. In the AppCenter toolbar, select **System**, then choose **Shut Down** in the pop-up menu. The Shut Down dialog box appears.
 - b. In the Shut Down dialog box, choose **Restart** in the drop-down list, then select **OK**.



AppCenter closes, then Windows will shutdown, and restart.

3. Watch for the “Windows Starting” message in white text and the message “Please select the operating system to start”, then immediately press **F8**.

NUM LOCK must be off before the arrow keys on the numeric keypad will function.

4. Use the arrow keys to highlight the **Safe Mode with Networking** option, and then press **ENTER**.

Windows starts in Safe mode.

5. Click **OK** in the Safe mode warning message.
6. Proceed to [“Scan and install critical Windows updates”](#).

Scan and install critical Windows updates

The Windows Update program is used in the procedure to scan the iVDR to determine if any critical updates are required. Afterward, you can download and install those updates manually. Your iVDR must have internet access to complete this procedure.

To scan and install critical updates:

1. Start the Windows Update program as follows:
 - a. Click **Start | Run**.
 - b. Type the following:
`c:\WINNT\system32\wupdmgr`
 - c. Click **OK**.
 Internet Explorer opens and connects to the Windows update web site.
2. On the web page, click **Scan for updates**.
 Wait for the scan to complete.
3. If there are “Critical Updates and Service Packs” required for your iVDR, follow the instructions on the web page to install them.



CAUTION: Only “Critical Updates and Service Packs” should be installed. Do not install other Windows 2000 or driver updates on your iVDR.

NOTE: If “Found New Hardware” messages appear, refer to “[Known issues](#)” CR55678 later in these release notes.

4. After installing critical updates, continue with [Part 2: “Special procedures if updating from 1.5.x or 1.6.x”](#):

Part 2: Special procedures if updating from 1.5.x or 1.6.x


If you are updating from 1.5.x or 1.6.x, perform one or more of the following procedures, otherwise proceed to [Part 3: “Update the M-Series media file system”](#).

Update XML parser software (Only if upgrading from 1.5.x)

If you are upgrading from iVDR software version 1.5.x, use the following steps to check the XML parser software version, and then update if needed.

To check and update the XML parser software:

1. Exit AppCenter as follows:
 - a. In the AppCenter toolbar, select **System**, then choose **Shut Down** in the pop-up menu.
 - b. In the Shut Down dialog box, choose **Exit to Windows** in the drop-down list, then select **OK**.
2. In the Windows taskbar, click **Start | Settings | Control Panel**, then select **Add/Remove Programs**.



3. Does **MSXML 4.0 SP2 Parser and SDK** appear in the programs list?
 - If “No”, proceed to step 4 to install the XML parser software.
 - If “Yes”, skip the rest of this procedure and go to the next procedure “[Uninstall existing version of M-Series software \(If updating from 1.5.x or 1.6.x\)](#)”.
4. Insert the *M-Series iVDR System Software* CD-ROM in the CD-ROM reader.
5. Use Windows Explorer to locate and run the *msxml.msi* installation file located in the **XML** folder on the CD-ROM.

The installation wizard Welcome page is displayed.
6. On the Welcome page, click **Next**, then follow the onscreen instructions to install the software. Use the **Install Now** option when asked.

NOTE: Do not modify the Customer Information text page when it is displayed.

7. Click **Finish** to close the installation wizard.

8. When prompted to restart the iVDR, click **No**. The restart at the conclusion of the Part 3 procedure is sufficient.
9. Continue with the next procedure “[Uninstall existing version of M-Series software \(If updating from 1.5.x or 1.6.x\)](#)”.

Uninstall existing version of M-Series software (If updating from 1.5.x or 1.6.x)

If you are upgrading from iVDR software version 1.5.x or 1.6.x, use this procedure to uninstall the existing version of M-Series software. This does not remove your media files from the iVDR. They will remain on the iVDR during the upgrade process.

To uninstall M-Series software:

1. Shutdown AppCenter as follows:
 - a. In the AppCenter toolbar, select **System | Shutdown**.
 - b. In the Shutdown dialog, select **Exit to Windows**, then **OK**.
AppCenter closes, and the desktop appears.
2. Click **Start | Settings | Control Panel**.
3. Open **Add/Remove Programs**.
4. Select **M-Series**, then click **Remove**.
5. Click **Yes** to confirm file deletion.
6. When prompted to restart the iVDR, click **No**. The restart at the conclusion of the Part 3 procedure is sufficient.
7. Proceed to the next section [Part 3: “Update the M-Series media file system”](#).

Part 3: Update the M-Series media file system

Use this procedure to update the media file system. You can access the installation program on the *M-Series iVDR Software* CD-ROM. Updating the file system does not harm existing media stored on the iVDR.

To update the M-Series media file system:

1. If AppCenter is open, exit AppCenter as follows:
 - a. In the AppCenter toolbar, select **System**, then choose **Shut Down** in the pop-up menu.
 - b. In the Shut Down dialog box, choose **Exit to Windows** in the drop-down list, then select **OK**.
2. Insert the *M-Series iVDR System Software* CD-ROM in the CD-ROM reader.
3. Use Windows Explorer to locate and run the *cvfs_win2k_2.1.2b91Simple.exe* installation file located in the CVFS folder on the CD-ROM.
The installation wizard Welcome page is displayed.
4. Accept the license agreement to start installation.
5. Click **Finish** when installation is complete.

6. When prompted to restart the iVDR, do the following:
 - If you are upgrading from version 1.5.x or 1.6.x, click **Yes**. You must restart now to finalize changes from this procedure and from earlier procedures.
 - If you are upgrading from versions 2.0 or higher, click **No**. The restart at the conclusion of the M-Series system software installation is sufficient.
7. Proceed to [Part 4: “Install M-Series system software”](#).

Part 4: Install M-Series system software

To install system software:



1. Insert the *M-Series iVDR System Software* CD-ROM in the CD-ROM reader.
2. Run *setup.exe*


You can click **Start | Run** in the Windows taskbar, and then use **Browse** to locate and select the *setup.exe* file in the **M** directory on the CD-ROM, then click **OK** to start installation.
3. In the Welcome dialog box, click **Next**, then follow onscreen instructions to install software.

NOTE: Be sure to install the software in the default *c:\profile* directory. Do not change it. Specifying another location will result in incorrect operation of the software.

4. After clicking **Finish** to close the install wizard, click **No** when prompted to restart the iVDR.
5. Power cycle the iVDR. This is necessary to update (flash) the codec board. To power cycle, do the following:
 - a. In the AppCenter toolbar, select **System**, then choose **Shutdown** in the pop-up menu. The Shutdown dialog box appears.
 - b. In the Shutdown dialog box, choose **Shutdown**, then select **OK**.
 - c. Wait for the iVDR to power off, then push the standby switch to start up. After Windows initializes, AppCenter automatically starts.

NOTE: If “Found New Hardware” messages appear, refer to “Known issues” CR55678 later in these release notes.

6. Confirm that the correct software versions are installed as follows:
 - a. Click the StatusPane button  in the AppCenter StatusBar. The StatusPane opens.
 - b. Select the StatusPane menu button , then choose **Show Versions**. Software versions are displayed.



c. Verify that the correct versions are installed.

7. Proceed to [Part 5: "Create a system disk image file"](#).

Part 5: Create a system disk image file

Create a system disk image as described in the *M-Series Service Manual*. This backup image can be used to restore the system disk. The procedure requires the *Recovery Program CD-ROM* that you received with your iVDR.

This concludes the software installation procedure.

Known issues

The following limitations are present in this M-Series iVDR Software 2.0.10 release. If you wish to obtain more information about these limitations, please mention the reference numbers that follow the description of each limitation. These known issues will be resolved in future releases.

“Found New Hardware” messages appear

- Description** After restarting the iVDR, “Found New Hardware” messages for the PCI Memory Controllers appear. This occurs on some systems after certain Windows “Critical Updates and Service Packs” have been installed. The timing of the hardware detection process changes with the Windows update such that now Windows detects Grass Valley hardware and incorrectly assumes it is new hardware. (CR55678)
- Workaround** From the Windows Control Panel open **System | Hardware | Device Manager**. In the tree view under **Other Devices** there are two “PCI Memory Controller” nodes. Right-click each **PCI Memory Controller** and select **Disable**. You can safely disable these in Windows without affecting iVDR functionality. Once disabled, the “Found New Hardware” messages no longer appear.

VGA monitor display settings

- Description** The Windows desktop is oversized and scrolls as you move the mouse. The display adapter card in the iVDR always starts in 640x480 mode even though the Windows screen size is set to 800x600.
- Workaround** Press the **CTRL+ALT+C** hot-key sequence when AppCenter is fully initialized after power-up to switch the display adapter card to 800x600 display settings. If you inadvertently select this key sequence on an iVDR with a front panel, press the **CTRL+ALT+L** hot-key sequence to return to 640x480 display settings which is required for front panel operation. All display hot-key sequences are described in the *M-Series User Manual*.

“Unsafe Removal of a Device...” message may appear during startup

- Description** Occasionally, during startup, the following Windows message may appear: “Unsafe Removal of a Device: PCI standard PCI-to-PCI bridge.” (CR47600)
- Workaround** Press **OK**, then restart the M-Series iVDR and complete startup without encountering the “Unsafe Removal” message.

Configuration files saved from previous versions are incompatible with 2.0.10

- Description** Configuration files created using previous versions of M-Series software will not work with version 2.0.10.
- Workaround** You must recreate configuration files after updating to 2.0.10.

Restore Defaults command does not restore factory settings

- Description If you uninstall M-Series software (required if updating from 1.5.x or 1.6.x) and then install version 2.0.10, using the restore defaults command makes no changes to the configuration settings. (CR49883)
- Workaround None.

Audio clipping indicator in Configuration Manager

- Description The audio clipping indicator in the Configuration dialog box does not function. The indicator is always gray.
- Workaround None.

Audio monitor in IEEE1394 record mode

- Description The rear panel audio monitor and the front panel headphone jack outputs the record channel audio input signal when the record channel is in IEEE 1394 record mode.
- Workaround None.

AVI output file format is always non-interleaved

- Description When exporting media to an AVI file, the user interface allows you to choose interleaved (type1) or non-interleaved (type2) AVI file format, however, the AVI file format is always non-interleaved (type2). (CR46219)
- Workaround None.

Channel information displayed only in full-screen mode

- Description The operation of the channel information setting in Configuration Manager is unclear. As designed, this setting only affects the channel Monitor in full-screen mode, not split-screen mode. (CR47436)
- Workaround NA.

Player: Signal status indicators do not operate

- Description The (V)(A1)(A2) signal status indicators in Player are not functional in this release. The indicators are always on.
- Workaround None.

Recorder: Audio status indicator problem when embedded audio selected

- Description In models M-222D and M-322D, when embedded audio is selected, all four audio status indicators in Recorder remain on even though the selected audio group contains less than four audio channels. (CR47333)
- Workaround None.

“VITC not present” message is always displayed in Configuration Manager

- Description In models M-122A and M-222A, the “VITC not present” message is always displayed in Configuration Manager even though VITC is detected and recorded as expected. (CR47411)
- Workaround None.

“Video is not present” message is always displayed in Configuration Manager

- Description In models M-122A and M-222A, the “video is not present” message is always displayed in Configuration Manager even though the SDI and Composite video signals are input and recorded as expected. (CR47412)
- Workaround None.

Playlist fails to transfer

- Description If a playlist you are attempting to transfer has one or more clips with only two audio tracks, the transfer fails. (CR53011)
- Workaround Make sure all clips in the playlist have four audio tracks.