

=====
RCP build 4.3b253
=====

Required software versions:

LGK/DSK v3.0b4 or v2.1.3b1
IS750 v3.0b4 or v2.0.2b10
IS300 v1.13.8.1b8
ISHD v1.13.8.1b8
Intuition v1.13.8.1b8

Known bugs:

- D-01279 Xpanel unable to browse Oxtel Clock file
- D-01484 (D-01481) RCP-BR can not arm and take an IntuitionXG layer
- D-01670 Pressing the rotary knob in the media browser does not speed up browsing
- D-01684 .oxa file should be supported by classic Intuition
- D-01781 The watch log page on the RCP web page sometimes stops updating the log file display
- D-01782 Main panel still shows loaded media names when channel down
- D-01788 (D-01815) Audio-related components still show up when not available
- D-01805 Software Updates can fail on RCP-BR on rare occasions
- D-01806 DSK-3901 Setup screen rotaries aren't assigned correctly
- D-01811 Station manager is slow with large configurations
- D-01812 RCP-BR requires restart after Imagestore crash
- D-01814 "Loading..." was showing for more than 3 minutes before the thumbnails show up.
- D-01817 FTB rate setting not working properly with "Fade to Black" button
- 5035 Crash in imstrend with Xpanel

- * D-01796 CGT & Setup Menu buttons are not selectable on DSK-3901
- * D-01797 Alarms info shows blank boxes for DSK-3901
- * D-01798 New IP address is not shown on RCP until after restart
- * D-01799 Setting Time on RCP make unwanted changes

=====
RCP build 4.3b252
=====

Required software versions:

LGK/DSK v3.0b4 or v2.1.3b1
IS750 v3.0b4 or v2.0.2b10
IS300 v1.13.8.1b8
ISHD v1.13.8.1b8
Intuition v1.13.8.1b8

=====
RCP build 4.3b251
=====

Required software versions:

LGK/DSK v3.0b4 or v2.1.3b1
IS750 v3.0b4 or v2.0.2b10
IS300 v1.13.8.1b8

ISHD v1.13.8.1b8
Intuition v1.13.8.1b8

=====
RCP build 4.3b250
=====

Required software versions:

LGK/DSK v3.0b4 or v2.1.3b1
IS750 v3.0b4 or v2.0.2b10
IS300 v1.13.8.1b8
ISHD v1.13.8.1b8
Intuition v1.13.8.1b8

=====
RCP build 4.3b249
=====

Required software versions:

LGK/DSK v3.0b4 or v2.1.3b1
IS750 v3.0b4 or v2.0.2b10
IS300 v1.13.8.1b8
ISHD v1.13.8.1b8
Intuition v1.13.8.1b8

=====
RCP build 4.3b248
=====

Required software versions:

LGK/DSK v3.0b4 or v2.1.3b1
IS750 v3.0b4 or v2.0.2b10
IS300 v1.13.8.1b8
ISHD v1.13.8.1b8
Intuition v1.13.8.1b8

=====
RCP build 4.3b247
=====

Required software versions:

LGK/DSK v3.0b4 or v2.1.3b1
IS750 v3.0b4 or v2.0.2b10
IS300 v1.13.8.1b8
ISHD v1.13.8.1b8
Intuition v1.13.8.1b8

* D-01666 DSK-3901 channels should not show media tabs.

=====
RCP 4.3 build 217
=====

* D-01377 No feedback is given if a file cannot be loaded.

=====
RCP 4.3 build 215
=====

- * D-01649 Memory leak in Xpanel2
- * D-01651 RCP-Splashscreen appears.
- * D-01652 RCP Web server revert panel function does not work.

=====
RCP 4.3 build 197
=====

- * D-01624 After deleting an event in the action editor subsequent deletes remove the wrong event.

=====
RCP 4.3 build 193
=====

- * D-01620 Vx_Button does not load correct number of OnClick events

=====
RCP 4.3 build 185
=====

- * D-01602 Animations are automatically cropped just after load.
- * D-01603 Default button has 2 states, but only one on click event.

=====
RCP 4.3 build 183
=====

- * B-01745 Add event on tab change
- * B-01736 Add event when alarm state changes
- * D-01600 Add option to supress dialog in shutdown action.
- * D-01601 Sort out up/down values for components.

=====
RCP 4.3 build 180
=====

- * B-01670 Station manager add new device types.

=====
RCP 4.3 build 173
=====

- * D-01571 RCP-BR Lockup if you pull out network cable and then put it back in again.
- * B-01659 RCP-BR panel add button to toggle to RCPInit

=====
RCP 4.3 build 172
=====

- * B-01717 Channel selector should display connection error.

=====
RCP 4.3 build 168
=====

- * D-01560 Reverting an RCP to its original panel after project path is wrong
- * D-01510 Loss of Network comms is not handled
- * B-01659 Add button to toggle to RCP Init

ReleaseNotes253.txt

- * D-01453 Fade to black/silence only work on 1st device in channel.
- * D-01393 Filter screen is not implemented correctly.
- * D-01295 Xpanel (RCP-BR) connection status not accurate.

=====
RCP 4.3 build 166
=====

- * D-01496 Xpanel-ImageStore image positioning.

=====
RCP 4.3 build 164
=====

- * D-01525 VO graph not changing with the settings in the config GUI

=====
RCP 4.3 build 161
=====

- * D-01491 time up startup progress bar to application
- * D-01490 panel: Turn on display a little later.

=====
RCP 4.3 build 158
=====

- * D-01335 DSK Load screen shows thumbnails of previous channel for short time.
- * D-01383 RCP should request tallies if communication is lost.
- * D-01495 0 tallies enabled too many times.
- * D-01510 Loss of Network comms is not handled
- * D-01512 Scripts do not seem to be exported with panels.

=====
RCP 4.3 build 156
=====

- * T-02545 Fixed requesting of tallies in actions
- * D-01295 Xpanel (RCP-BR_ connection status not accurate.

=====
RCP 4.3 build 149 13th July 2009
=====

- * D-01458 RCP-BR lock-up in media browser
- * D-01498 RCP Configurator tool shows warning before exporting project
- * B-01242 Keyer image thumbnail wrong when no image in keyer

=====
RCP 4.3 build 140 3rd July 2009
=====

- * B-01558 Create combo to brighten/dim Leds please note that this also requires the latest panels.
- * D-01463 LGK DSK5 store loading not implemented properly (not handling only 4 stores) please note that this requires the latest panels.

=====
RCP 4.3 build 138 2nd July 2009
=====

- * D-01375 RCP button LEDs wrong in top bar (Please note this requires the latest panels)

ReleaseNotes253.txt

This version contains a modified firmware which contains a new variant of the tick count.

=====
RCP 4.3 build 137 1st July 2009
=====

Modified threading in the image browser to make it much more difficult to lock up.

=====
RCP 4.3 build 135 30th June 2009
=====

- * D-01469 Macro hard buttons stay lit when changing channels
- * D-01428 Cropping is not queried upon entering menu
- * D-01471 Clip, Gain and Transparency are not queried
- * D-01426 Clip and Gain should never show a number higher than 940
- * D-01425 Transparency setting upper limit is 511 instead of 512

=====
RCP 4.3 build 134 30th June 2009
=====

- * D-01459 Channels not shown in channel selector working view
- * D-01468 No alarms shown for devices other than the RCP
- * D-01312 RCP-BR: Premade system panel not working.
- * D-01367 All button lights should go out on shutdown NOTE This will need new version of Init RCP
- * D-01489 RCP-BR: Firmware re-introduce debug

=====
RCP 4.3 build 133 29th June 2009
=====

=====
RCP 4.3 build 126
=====

- * D-01462 xpanel cannot always grab a channel

=====
RCP 4.3 build 125 24th June 2009
=====

- * D-01470 Intuition sometimes opens image tab in browser
- * D-01376 LKG shows no load live
- * D-01433 RCP alarm dialogue, relaxed 12v alarm voltages and removed rpm and temperature suffix.

=====
RCP 4.3 build 122 23rd June 2009
=====

- * Includes latest firmware as released in 4.3b121a5
- * Reduced number of keyer commands sent to ImageStore including those for keyers that do not exist.
- * D-01443 VO thumbnail does not represent the VO settings correctly.

=====
RCP 4.3 build 121 18th June 2009
=====

- * Further improvements to the firmware to resolve startup issues.

ReleaseNotes253.txt

- * Media browser is now threaded.
- * Media browser now should show all media when opened.

=====
RCP 4.3 build 118 16th June 2009
=====

- * New version of firmware - this needs testing to measure the reliability of the firmware startup.
- * Shutdown and restart should now work with the new Embedded XP image.