

Acappella ROUTING SYSTEM	
Release Notes Addendum	
• SOFTWARE VERSION 3.2.0  071869400 MARCH 2009	



## **Contacting Grass Valley**

International Support Centers	France 24 x 7	+800 8080 2020 or +33 1 48 25 20 20	United States/Canada 24 x 7	+1 800 547 8949 or +1 530 478 4148		
Local Support Centers (available during normal business hours)	Asia	Asia       Hong Kong, Taiwan, Korea, Macau: +852 2531 3058 Indian Subcontinent: +91 22 24933476         Southeast Asia/Malaysia: +603 7805 3884 Southeast Asia/Singapore: +65 6379 1313         China: +861 0660 159 450 Japan: +81 3 5484 6868				
	Australia and New Zealand: +61 1300 721 495			<b>Central/South America:</b> +55 11 5509 3443		
	Middle East: +971 4 299 64 40 Near East and Africa: +800 8080 2020 or +33 1 48 25 20 20					
	Europe         Belarus, Russia, Tadzikistan, Ukraine, Uzbekistan: +7 095 2580924 225 Switzerland: +41 1 487 80 02           S. Europe/Italy-Roma: +39 06 87 20 35 28 -Milan: +39 02 48 41 46 58 S. Europe/Spain: +34 91 512 03 50           Benelux/Belgium: +32 (0) 2 334 90 30 Benelux/Netherlands: +31 (0) 35 62 38 42 1 N. Europe: +45 45 96 88 70           Germany, Austria, Eastern Europe: +49 6150 104 444 UK, Ireland, Israel: +44 118 923 0499					

Copyright © Thomson, Inc. All rights reserved. This product may be covered by one or more U.S. and foreign patents.

#### **Grass Valley Web Site**

The <u>www.thomsongrassvalley.com</u> web site offers the following:

**Online User Documentation** — Current versions of product catalogs, brochures, data sheets, ordering guides, planning guides, manuals, and release notes in .pdf format can be downloaded.

**FAQ Database** — Solutions to problems and troubleshooting efforts can be found by searching our Frequently Asked Questions (FAQ) database.

**Software Downloads** — Download software updates, drivers, and patches.



#### **END-OF-LIFE PRODUCT RECYCLING NOTICE**

Grass Valley's innovation and excellence in product design also extends to the programs we've established to manage the recycling of our products. Grass Valley has developed a comprehensive end-of-life product take back program for recycle or disposal of end-of-life products. Our program meets the requirements of the European Union's WEEE Directive, the United States Environmental Protection Agency, and U.S. state and local agencies.

Grass Valley's end-of-life product take back program assures proper disposal by use of Best Available Technology. This program accepts any Grass Valley branded equipment. Upon request, a Certificate of Recycling or a Certificate of Destruction, depending on the ultimate disposition of the product, can be sent to the requester.

Grass Valley will be responsible for all costs associated with recycling and disposal, including freight. However, you are responsible for the removal of the equipment from your facility and packing the equipment to make it ready for pickup.

For further information on the Grass Valley product take back system please contact Grass Valley at + 800 80 80 20 20 or +33 1 48 25 20 20 from most other countries. In the U.S. and Canada please call 800-547-8949 or 530-478-4148, and ask to be connected to the EH&S Department. Additional information concerning the program can be found at: www.thomsongrassvalley.com/environment



# Acappella Release Notes Addendum

This release notes addendum provides further information for the Acappella A84HR-CLP – 8x4 HD Router with Clean Switch. Currently, this router is used primarily for the Indigo A/V Mixer Input Expansion options. In this capacity, only HD video sources are used. The information below is provided for a current issue when using SD video sources.

### **Known Software Problems**

Please note the following when using SD sources on the above router model:

The Frame Sync function in the Acappella models listed above is currently proven and tested for use only with HD input video sources. The frame sync is capable of SD input video operation, but it is not warranted to work properly in this release. If the frame sync does not pass SD input video correctly, there are two workarounds that should fix the problem:

- 1. Change the field rate setting from **Use Reference** to **59.94Hz** or **50Hz** on the Frame Sync web page, depending on the field rate of the video passed through the Acappella and/or the reference signal attached to it. This change forces the video detector to work properly.
- 2. While trying to pass SD video through either output channel 1 or output channel 2 of the Frame Sync function, ensure that there is an HD or SD video signal on the other Frame Sync channel as well. This change forces valid signals to the timing recovery circuitry when passing SD video.

Correct operation of the Frame Sync function will result from these changes.