



AMX-3981

NOTE: The iControl compatibilities shown below are estimated initial support. iControl versions that are older than those specified may prevent the GUI from opening or may work with bugs and limited features.

FIRMWARE VERSION: 201

Release date: [2010-09-28](#)

iControl compatibility: [v3.7 \(build 21\)](#) +

iControl Solo compatibility: [v3.7](#)

RCP-200 compatibility: [v 1.10](#)

Custom software compatibility: [NA](#)

Hardware incompatibility: [This firmware applies to all existing hardware assembly.](#)

BUGFIXES

Bug#	Description
29024	Corrupted video in 3G level-B

ENHANCEMENTS & NEW FEATURES

Bug#	Description
-	The audio/video fingerprint generation. Available in iControl 4.0 only.

KNOWN BUGS & LIMITATIONS

Bug#	Description
------	-------------



FIRMWARE VERSION: 200

Release date: [2010-06-30](#)

iControl compatibility: [v3.70](#)

iControl Solo compatibility: [v3.70](#)

RCP-200 compatibility: [N/A](#)

Custom software compatibility: [NA](#)

Hardware incompatibility: [This firmware applies to all existing hardware assembly.](#)

BUGFIXES

Bug#	Description
------	-------------

ENHANCEMENTS & NEW FEATURES

Bug#	Description
-	The test tone inserter for out of service lip-sync measurement
-	The on-board SIMM-72 socket is enabled and the following modules are supported
-	MOD-DOLBY-ENC-E (v1.1.2.0/v1.1.3.3)
-	MOD-DOLBY-ENC-D (v1.0.2.5/v1.0.2.7)
-	MOD-DOLBY-DEC (v1.2.3.2/v1.2.0.12)
-	MOD-LA-DUP-701
-	MOD-LA-ALC-x (2/6/8-v1.3.0.0/v1.3.1.0/v1.4.0.0)
-	MOD-LA-ALC-x-DUP (2/6/8-v1.3.0.0/v1.3.1.0/v1.4.0.0)
-	MOD-JA-ALC-x (2/6/8-v1.5.0.0)
-	MOD-JA-ALC-x-DUP (2/6/8-v1.5.0.0)
-	The loudness measurement option is available
-	Time code is automatically and frame-accurately generated when GPI embedding has been enabled and no valid time code has been detected. This generated time code is forced to 00:00:00:00 and does not increment.
-	A GPI latch mode allows the user to maintain the GPI output levels when no valid time code with embedded GPI data has been detected or to simply release the GPI output levels during this time

KNOWN BUGS & LIMITATIONS

Bug#	Description
-	The audio/video fingerprint generation is not available.