



## FRS-3901

**NOTE:** The iControl compatibilities shown below are estimated initial support. iControl versions that are older than those specified may prevent the GUI from opening or may work with bugs and limited features.

### VERSION: 300

**Release date:** [2013-04-18](#)

**iControl compatibility:** [v4.42 and up](#)

**iControl Solo compatibility:** [4.42](#)

**RCP-200 compatibility:** [Not supported](#)

**Hardware incompatibility:** [This firmware applies to all existing hardware assembly.](#)

### ENHANCEMENTS & NEW FEATURES

Ref#	Description

### BUGFIXES

Bug#	Description

### KNOWN BUGS & LIMITATIONS

Bug#	Description
<a href="#">24794</a>	<b>Metadata packet insertion during 3G Level B outputs.</b> During 3G Level B operation, there may be situations where output Ancillary Time Code (ATC)



## *Release Note*

---

	<p>packets will be inserted on Link B. Asynchronous sources with respect to the reference may insert ATC packets on Link B instead of Link A. If the source and reference are synchronous, then ATC packets may find themselves on Link B depending on the source's timing with respect to the reference. An aligned input places ATC packets on the proper link (Link A).</p>
--	--

	<p>This situation does not occur when no reference is installed.</p>
--	--