



# Profile LVS Event Management System Basic Feature Set Version 3.1.15 Release Notes

## Table of Contents

<i>Grass Valley Group Product Support</i> .....	2
<i>Welcome to LVS</i> .....	3
<i>System Requirements</i> .....	3
<i>Installing the Software</i> .....	4
<i>New Features in Version 3.1.15</i> .....	4
<i>Improved Jog/Shuttle Knob Response</i> .....	4
<i>Dynamic Configuration Changes</i> .....	4
<i>Disk Cleanup Cancel</i> .....	4
<i>LVS Software and Other Applications</i> .....	5
<i>Clip Compatibility</i> .....	5
<i>Setup Limitations</i> .....	5
<i>Known Problems</i> .....	6

Copyright © 2000 Grass Valley Group Inc. All rights reserved. Printed in the United States of America.

This document may not be copied in whole or in part, or otherwise reproduced except as specifically permitted under U.S. copyright law, without the prior written consent of Grass Valley Group Inc., P.O. Box 59900, Nevada City, California 95959-7900

Grass Valley, GRASS VALLEY GROUP, Profile and Profile XP are either registered trademarks or trademarks of Grass Valley Group in the United States and/or other countries. Other trademarks used in this document are either registered trademarks or trademarks of the manufacturers or vendors of the associated products. Grass Valley Group products are covered by U.S. and foreign patents, issued and pending. Additional information regarding Grass Valley Group's trademarks and other proprietary rights may be found at [www.grassvalleygroup.com](http://www.grassvalleygroup.com) <<http://www.grassvalleygroup.com>>.

Product options and specifications subject to change without notice. The information in this manual is furnished for informational use only, is subject to change without notice, and should not be construed as a commitment by Grass Valley Group. Grass Valley Group assumes no responsibility or liability for any errors or inaccuracies that may appear in this publication.



## Grass Valley Group Product Support

You can get technical assistance, check on the status of problems, or report new problems by contacting our Product Support Group.

### United States and Canada

Monday–Friday 5:30AM–5:00PM Pacific Time  
(800) 547-8949

### Europe

Monday–Friday 9:00AM–5:30PM

France	01 45 29 73 00	United Kingdom	01628 405830
Germany	49 221 1791 234	Other	+44 1753 218 777
Italy	02 25086606		

### Asia and South America

Australia	02-9888 0100	Japan	81-3-3448-3111
- from overseas	61-2-9888 0100	Korea	82-2-528-5299
Beijing	86-10-62351230 ext. 711	Mexico	52-5-666-6333
Brazil	55-11-3741-8422	Singapore	65-356-3900
Hong Kong	852-2585-6579	Taiwan	886-2-27571571

### World Wide

**24-hour Emergency Hotline (530) 478-4148** (Contract and warranty customers)

<b>World Wide Web</b>	<a href="http://www.grassvalleygroup.com/support/">http://www.grassvalleygroup.com/support/</a>
<b>FTP Site</b>	<a href="ftp.grassvalleygroup.com">ftp.grassvalleygroup.com</a>
<b>Users Group</b>	<a href="mailto:profile-users@grassvalleygroup.com">profile-users@grassvalleygroup.com</a>

---

# Welcome to LVS

Grass Valley Group is pleased to present Version 3.1.15 of the Profile LVS Event Management System software for use with the Profile LVS Live Controller.

The LVS Event Management System software is available in two versions:

- Basic Feature Set, included with the Profile LVS Live Controller.
- Enhanced Feature Set (LVSESW), available as an option.

The *Profile LVS Event Management System Instruction Manual* (071-8002-00) describes Version 3.1 of both of these feature sets.

These *Release Notes* detail the changes and new features in Version 3.1.15, and provide up-to-the-minute information about the Profile LVS Live Controller and the Basic Feature Set software *only*. Please consult the *LVS Enhanced Feature Set Release Notes* for the latest information about the LVS ESW software.

This software was thoroughly tested before release. However, you may encounter some operational limitations or have suggestions on how to improve the product. Please contact Grass Valley Group Product Support if you have any problems or comments.

## System Requirements

The LVS Version 3.1.15 Basic Feature Set software operates on all Profile systems, including PDR 100 (with EDR boards), PDR 200, PDR 300, and PDR 400.

***NOTE: The LVS Event Management System uses JPEG codecs only. You cannot allocate MPEG or DVCPRO resources to LVS operations.***

Table 1 summarizes the minimum and recommended software versions to ensure optimum LVS Event Management System operation. Contact Grass Valley Group Support if you do not have the required software version.

**Table 1: LVS Basic Feature Set 3.1 Software Compatibility**

Software	Minimum	Recommended
Profile System Software	2.5.6.2	2.5.6.2
Live Controller Firmware	1.20	2.0



---

## Installing the Software

1. Install Profile System Software Version 2.5.6.2 or higher. Refer to the Release Notes that accompany the software for installation instructions.

***NOTE: You must restart your Profile system after installing Profile System Software and before installing the LVS software.***

2. Install the LVS Basic software as described in the *Profile LVS Event Management System Instruction Manual*.

***NOTE: If you're installing the LVSESW Enhanced software, you don't need to install the LVS Basic software first.***

## New Features in Version 3.1.15

The following new features have been implemented in Version 3.1.15 of the LVS Basic Feature Set software.

### Improved Jog/Shuttle Knob Response

Version 3.1.15 provides customizable Jog/Shuttle knob response times so that you can adjust the LVS Live Controller speed to your personal preference. To benefit from this improved performance, your LVS Live Controller must be running Firmware version 2.0.

All new LVS Live Controllers are now shipped with Firmware version 2.0. If you wish to upgrade your Live Controller to benefit from the improved Jog/Shuttle knob response, contact your sales representative and ask about the LVS Live Controller Firmware upgrade kit, part number 050-3420-XX.

### Dynamic Configuration Changes

Configuration settings such as pre-roll and post roll, audio monitoring, maximum shuttle speed, and several others can now be changed without restarting the LVS software. You still have to restart the software for fundamental configuration changes such as codec assignments.

### Disk Cleanup Cancel

This may help you preserve material that you didn't intend to remove.

---

## LVS Software and Other Applications

You should avoid using other Profile applications such as VdrPanel at the same time as LVS software is running. This will prevent resource conflicts which may cause performance problems. You may want to remove VdrPanel from the Startup group or from the *pdrstart.bat* file.

## Clip Compatibility

This version of the LVS software creates clips which can't be played with other Profile applications, nor can you use clips created with other Profile applications in the LVS Event Management System. Version 3.1.15 of the LVS Enhanced Feature Set software (LVS ESW) allows you to create PDR Movies in your LVS session. These movies can be used by other Profile applicaitons.

## Setup Limitations

The LVS **Setup | Normal** command doesn't check for configurations which are not supported by your Profile Video Disk Recorder. You must ensure that your system has the capabilities you select in the Setup dialog box.

If you create a configuration which is not supported by your system, clicking OK will result in a progress bar which remains on the screen indefinitely. You must use the Windows NT Task List (Ctrl+Esc) to end the task and remove the progress bar. You must then restart the LVS software and establish a valid configuration.



---

## Known Problems

- |            |  |
|------------|--|
| Problem    | Occasionally, you may be unable to make space available by running Disk Cleanup.   |
| Workaround | Move all the scenes and highlights that you wish to keep to the Library Window. Then shut down and restart your LVS session. When prompted, delete scenes and highlights from previous sessions. This will free up all available disk space. |
| Problem    | The Playlist video output may not show the correct cue point after a trim operation in the Scene Information Window.   |
| Workaround | Manually recue the event after trimming it in the Scene Information Window.  |
| Problem    | Individual fader presets are not retained when the faders are grouped; the faders reset to matching levels.  |
| Workaround | Grouped fader controls operate with matching fader levels only. Individual settings are not supported.   |
| Problem    | Playback of a Playlist stops or doesn't play as expected when the Playlist is changed from the Scene Information Window.   |
| Workaround | Allow at least five seconds between a change to a Playlist event and the time the event will be played out.  |
| Problem    | On some systems, changing from Step to Continuous playback in Playlist mode causes the playback to stop.   |
| Workaround | Restart the playback. Avoid switching from Step to Continuous on air.  |
| Problem    | After a change to the system configuration, all scenes and highlights not stored in the Library are automatically deleted when the LVS application is restarted.   |
| Workaround | Avoid changing video configurations if you have scenes that you want to preserve. Other configuration changes will not cause your scenes to be deleted.  |