

DVI-Ramp2

IMPORTANT NOTICE



The firmware of the DVI-Ramp2 is field upgradeable. Currently, as a first phase of implementation, only a limited feature set has been activated.

Please find below the list of features that are **not currently implemented**:

- **“DVI-D IN B” input not yet functional:** only DVI-D IN A is operational (DVI-D IN B will be used for fill+key applications, more-than-8-bits DVI, ...)
- **No “Scaler”:** only pixel-to-pixel extraction mode is implemented.
- **No ethernet functionality**

These and other features will be activated by a firmware update that will be available from Miranda's technical support.

If you have any questions, please contact Miranda Technical Support as shown under *Support* on the web site

Thank you for choosing Miranda.